

# ADEQ

## Hazardous Waste Division

### Technical Branch

### Trip Report

<b>Project</b>	Former Cedar Chemical Facility
<b>Location</b>	West Helena, AR
<b>Date</b>	06/27/2012
<b>Time</b>	day trip
<b>Reason</b>	Observe Site Conditions
<b>ADEQ personnel</b>	Clay McDaniel, Jim Rigg, Mark Lawler
<b>Facility personnel</b>	Gary Hill – Harcross employee Stanley Herrington – Harcross Site Manager
<b>Activity Summary</b>	Took tour of the facility to observe compliance
<b>Action Items Summary</b>	<ul style="list-style-type: none"> <li>• We toured the admin building to observe the status of the documents. There are estimated to be 680 boxes of documents and they are in good condition. Sagging ceiling tiles were observed (see photo #1) but the apparent leak has not yet impacted the documents.</li> <li>• An unidentified monitoring well did not have a lock on it (see photo #2).</li> <li>• The soil pile from excavation of the sump is still located on the former Unit 4 foundation (see photo #3). It has been 119 days between when it was 1<sup>st</sup> discovered and this site visit. Stan said a sample from the soil pile was taken for analysis to ETC in Memphis. It was then supposed to be taken to clean harbors, but is still in negotiation between clean harbors and John Peiserich.</li> <li>• There are around 18 buckets of IDW purge water from July 2010 sampling event. Each bucket was labeled to identify the monitoring well it came from</li> <li>• Harcross has fixed cracked asphalt that was requested in ADEQ letter dated May 31, 2012 (see photo #4).</li> </ul>
<b>Anticipated follow-up</b>	Harcross has not provided ADEQ with bi-weekly updates on the status of the soil pile or met the 45 day deadline to respond to remove the IDW (expired on 05/18/12). A letter should be sent to Harcross to site them of their failure to follow up ADEQ's request.
<b>Other</b>	


### Route to:

<b>ADEQ personnel review</b>	<b>date</b>
------------------------------	-------------

Annette Cusher	7/6/2012
Tammie Hynum	

# Arkansas Department of Environmental Quality

## Official Photograph Log

Ceiling In Admin Building	
<b>Photo # 1</b>	<b>Photographer:</b> Clay McDaniel, ADEQ
<b>Date:</b> Wednesday, June 27, 2012	<b>Witness:</b> Mark Lawler, ADEQ
	

Monitoring Well With No Lock (located in the boneyard area)	
<b>Photo # 2</b>	<b>Photographer:</b> Clay McDaniel, ADEQ
<b>Date:</b> Wednesday, June 27, 2012	<b>Witness:</b> Mark Lawler, ADEQ
	

Soil Pile from Sump Excavation (located on the former Unit 4 footprint)	
<b>Photo # 3</b>	<b>Photographer:</b> Clay McDaniel, ADEQ
<b>Date:</b> Wednesday, June 27, 2012	<b>Witness:</b> Mark Lawler, ADEQ

# Arkansas Department of Environmental Quality

## Official Photograph Log



### Newly Paved Area to Replace Cracked Asphalt

**Photo #** 4

**Photographer:** Clay McDaniel, ADEQ

**Date:** Wednesday, June 27, 2012

**Witness:** Mark Lawler, ADEQ

